Figure: 28 TAC §34.1302(a)

| Citation | Violation | Fine | Citation | Violation | Fine |
|------------------|--|-------------------------|---------------|--|----------------------|
| | License and Registration | | 34.517(e) | Fixed system not installed or serviced by Type A or EPL | \$2,000.00 |
| | | | | | |
| 6001.152(a) | Branch office registration certificate required | \$1,000.00 | | Installation and Service | |
| 6001.161(a) | Apprentice permit required | \$500.00 | 34.517(a)(1) | Portable extinguisher not installed/serviced/maintained IAW manufacturer's instructions | \$50.00- \$500.00 |
| 6001.251(a)(1) | No registration certificate (portable) | \$3,000.00 | 34.517(a)(2) | Service tag not attached upon completion | \$250.00 |
| 0001.231(a)(1) | 140 registration certificate (portable) | ψ3,000.00 | 34.317 (a)(2) | Cervice tag not attached upon completion | Ψ230.00 |
| 6001.251(a)(2) | No registration certificate (fixed) | \$3,000.00 | 34.517(b)(1) | Fixed system not planned/installed/serviced IAW "manufacturer's Instructions | \$50.00- \$500.00 |
| | | | | | |
| 6001.251(a)(3) | No license | \$3,000.00 | 34.517(b)(2) | Installation label not affixed to system upon completion | \$250.00 |
| 34.510(e)(10)(A) | No C registration for U.S. DOT extinguishers | \$2,000.00 | 34.517(b)(3) | Installation label not signed and affixed to system by Type A or PL licensee (non pre-engineered) | \$500.00 |
| 34.510(e)(10)(B) | No verification of U.S. DOT registration | \$2,000.00 | 34.517(b)(3) | Licensee who signed label was not at final test (non pre-engineered) | \$500.00 |
| 34.510(f) | Registration information not displayed on vehicle | \$250.00 | 34.517(b)(4) | Service tag not attached after service completion | \$500.00 |
| 34.511(f)(1) | Licensee not employed by registered firm | \$2,000.00 | 34.517(f) | Pre-engineered kitchen system not UL300 | \$2,000.00 |
| 34.511(f)(3) | Failure to notify SFMO of termination of employee within 14 days | \$250.00 | 34.517(h) | Fusible link manufacturer date not within 1 year | \$500.00 |
| 34.513 | Alteration of certificates, licenses, or permits | \$3,000.00 | 34.517(i) | Actuation cartridge not dated | \$500.00 |
| 34.514(a)(5)(b) | Failure to maintain proof of insurance on file at SFMO | \$750.00 | 34.517(j) | Tamper indicator not dated | \$500.00 |
| | Adopted Standards | | 34.518(a) | Shop drawings not on file or not given to owner | \$500.00 |
| 34.517(a)(1) | Failure to abide by adopted standards or manufacturers requirements for portable extinguishers | \$50.00 - \$500.00 | 34.518(c) | Shop drawings not signed by EPL | \$500.00 |
| 34.517(b)(1) | Failure to abide by adopted standards or manufacturers requirements for fixed extinguishers | | 34.519(a) | Service tag not completed in detail | \$250.00 |
| | Location and Business Practices | | 34.520(b) | Service tag not completed each time service is performed | \$500.00 |
| 34.510(d) | Failure to maintain business location | \$500.00 | 34.521(a) | Owner not notified immediately of impaired portable or fixed extinguisher | \$500.00 |
| 34.510(e) | Failure to maintain shop | \$50.00- \$500.00 | 34.521(a) | AHJ not notified within 24 hrs of impaired portable or fixed extinguisher | \$500.00 |
| 6001.252(a)(3) | Misrepresentation of goods or services | \$250.00- \$1,000.00 | 34.521(a) | Written notice to owner; copy of written notice to AHJ within 3 days | \$500.00 |
| 34.517(c) | Pre-engineered system not installed or serviced by authorized licensee | \$2,000.00 | 34.521(a) | Failed to attach red tag to impaired extinguisher | \$500.00 |
| 34.517(e) | Fixed system not planned by EPL or professional engineer | \$2,000.00 | 34.521(a) | Service tag attached to impaired extinguisher | \$1,000.00 |

| 34.514(a)(5)(B) | Lapse of Insurance | | | | |
|-----------------|--------------------|---|--------------|---|----------------|
| Months | Punitive | + | Amount saved | | Total |
| 0 - 1 | \$200 | + | \$125 | = | Warning Letter |
| 1 - 2 | \$500 | + | \$250 | = | \$750 |
| 2 - 3 | \$500 | + | \$375 | = | \$875 |
| 3 - 4 | \$500 | + | \$500 | = | \$1,000 |
| 4 - 5 | \$500 | + | \$625 | = | \$1,125 |
| 5 - 6 | \$500 | + | \$750 | = | \$1,250 |
| 6 - 7 | \$750 | + | \$875 | = | \$1,625 |
| 7 - 8 | \$750 | + | \$1,000 | = | \$1,750 |

| 8 - 9 | \$750 | + | \$1,125 | = | \$1,875 |
|---------|-------|---|---------|---|---------|
| 9 - 10 | \$750 | + | \$1,250 | = | \$2,000 |
| 10 - 11 | \$750 | + | \$1,375 | = | \$2,125 |
| 11 - 12 | \$750 | + | \$1,500 | = | \$2,250 |